Arkansas Department of Environmental Quality
Solid Waste Management Division
Other Report Form

Activity	Voided Facility Inspection	**PDS ID**	082575
Site Name	ElDorado Class 1	**County**	Union
Location	N 33 12' 28" W 92 36' 51" 764 Industrial Park Road ElDorado, AR	**Date**	2/19/2015

COMMENTS

Voided Permit # 0023-S **AFIN** 70-00119

On February 19, 2015, I inspected the voided ElDorado Class 1 Landfill site. The site is currently occupied by the ElDorado Compost facility and ElDorado radio control airplane club. The vegetation is well established and maintained by the ElDorado Sanitations Department. Settled areas with standing water were observed on the cap. Noted one erosion reel with exposed waste on the southwest corner slope. One leachate leak was noted on the west slope.

Signature of Inspector	Amy Eddy	**Date**	2/19/2015

Other Report Form 3-18-10

Permit # 0023-S (Voided) Photos 1 & 2





Permit # 0023-S (Voided) Photos 3 & 4





Permit # 0023-S (Voided) Photos 5 & 6





Permit # 0023-S (Voided) Photos 7 & 8





Permit # 0023-S (Voided) Photos 9 & 10





Permit # 0023-S (Voided) Photos 11 & 12





Permit # 0023-S (Voided) Photos 13 & 14





Permit # 0023-S (Voided) Photos 15 & 16



