ARKANSAS
ENERGY & ENVIRONMENT

7/19/2021

Veronica Creer
City of El Dorado Mayor
P. O. Box 2170
El Dorado, AR 71730-2170

RE: Inspection conducted on July 15, 2021
AFIN 70-00119
Permit Number 0005-SCYW

Dear Mayor Creer:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us.
.

Sincerely,

Gerry Eddy
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

cc: Scott McWilliams, Compliance Manager, Office of Land Resources

ARKANSAS
ENERGY & ENVIRONMENT

Division of Environmental Quality
Office of Land Resources - Solid Waste Management
Compost Inspection

Site Name	City of El Dorado Yard Waste Composting	**County**	Union	**AFIN**	70-00119
Facility Address	764 Industrial Park Road	**Phone number**	870-881-4185	**Permit number**	0005-SCYW
Permittee Address	204 North West Ave. ElDorado, AR 71730	**E-Mail Address**	mayorsmith-creer@eldoradoar.org	**PDS #**	116804
Date	**7/15/2021**	**Entry time**	**1025**	**Exit time**	**1040**

Classification Type	**X**	**Y – Yard Waste**		**O – Source Separated Organic Waste**		**S – Mixed Solid Waste**

Regulation 22 – Operational Standards

Category 1

	Regulation	Item Description	Comments
	806(a)(4);(b)(9)	**Site access, all-weather roads, signage**	
	808(a)(b)(c)	**Record keeping and Reporting**	
	805(b)(1);805(c)(5)	**Operating records retained**	
	808(a)(4);(b)(2)	**Type and source of incoming waste; monitoring quantity**	
	805(b)(2);(c)(6)	**Conform to operations narrative/plan**	
	804	**Adequate plans for monitoring, sampling, testing, contingency**	
	805(b)(1);(c)(5)	**Facility has operating plan**	

Category 2


	Regulation	Item Description	Comments
	805	**Operations in accordance with permit documents**	The facility is currently not operating..
	805(c)(3) *Type O&S*	**Processing of incoming waste within 3 days**	
	806(a)(5);(b)(10)	**Adequate methods to manage odors**	
	806(a)(5);(b)(10)	**Adequate controls to manage vectors, dust, and litter**	
	805(a)(2)	**Operations follow acceptable methods**	
	807(a)(b)(c);808(b)(9) *Type O&S*	**Testing of run-off and compost**	
	805(c)(2) *Type O&S*	**Daily temperature readings recorded**	
	805(c)(4) *Type O&S*	**Finished compost not sold within 6 months**	
	806(a)(6);(b)(11)	**Methods to handle and remove unacceptable waste**	
	806(a)(2);806(b)(3)	**Adequate composting area surface, slope and drainage**	
	805(a)(3)	**Operations performed by licensed operator**	
	808(a)(4);(b)(2)	**Monitoring types of wastes received**	

Category 3

	Regulation	Item Description	Comments
	809(a)(b)(c)	Compost Utilization	
	805(c)(1) *Type O&S*	Compost process meets PFRP	
	805(a)(1)	Operations preclude pollution	
	806(a)(3);(b)(7)	Adequate controls for storm water, runoff, and NPDES	
	805(c)(3) *Type O&S*	Adequate leachate and NPDES control measures	
	806(b)(8) *Type O&S*	Leachate collection and removal system	

Regulation 22 - Records

804(b)(8)(i)(C)(D)	Date of last random inspection for unauthorized hazardous waste	N/A	Total number for month	N/A
808(b)(11)	Date of last quarterly/semi-annual/annual report	7/15/2021	Site Conditions	Dry
808(a)(4)(b)(2)	Last months reported waste received	0	Weather Conditions	Clear

Operator Name & Number	Anthony Traylor 003975		Signature of Inspector				
Exit Interview Conducted with	Anthony Traylor, Operator	Method	Telephone	Date	7/15/2021	Time	1220

Division of Environmental Quality (DEQ)
Official Photograph Sheet

Location	City of El Dorado Yard Waste Composting			**Permit**	0005-SCYW	**AFIN**	70-00119
Photographer	Gerry Eddy, Inspector	GE		**Witness**	N/A		
Photo #	1	**Of**	1	**Date**	7/15/2021	**Time**	1032
Description	View of the site.						

