



ARKANSAS

ENERGY & ENVIRONMENT

6/28/2022

Ms. Sarah Palazzi
Albemarle Corporation
P. O. Box 729
Magnolia, AR 71753-0729

RE: Inspection conducted on June 21, 2022
AFIN 14-00028
Permit Number 0175-S

Dear Ms. Palazzi:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink that reads 'Gerry Eddy'.

Gerry Eddy
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 3 Landfill Inspection Form**

Site Name	Albemarle Corporation Class 3 Landfill	County	Columbia	AFIN	14-00028
Facility Address	2270 Hwy 79 Magnolia, AR	Phone #	870-235-6000	Permit #	0175-S
Permittee Address	P. O. Box 729 Magnolia, AR 71753	Email Address	sarah.palazzi@albemarle.com	PDS #	120766
Date	6/21/2022	Entry Time	0821	Exit Time	0922

Operational Standards

Category 1

Regulation	Item Description	Comments
522(a)	Annual Compliance Inspection by Registered Professional Engineer	

Category 2


Regulation	Item Description	Comments
510(a)	Operations in Accordance with Permit Documents	
516(c)	Adequate All Weather Operational Roads	
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
510(b)	Operations by Licensed On-site Operator at all Times	
510(d)	Waste Spread and Compacted as Unloaded	
518	Surface Water Control	
517(a)(b)	Run-on/off Control System Present and Adequate	
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
510(n)	Leachate Leaks or Evidence of Leachate Seepage	
526	Survey Controls	
529	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
518	Cause Discharge/Leachate Discharge Leaving Landfill	
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/off Lined Area	

Records

Date of Last Annual Report	7/6/2021	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	N/A	Previous Quarter Waste Received	4.5 Tons

Operator Name & Number	Stephen Stamps 004197	Signature of Inspector	
Exit Interview Conducted with	Stephen Stamps	Method	In Person
		Date	6/21/2022
		Time	0922