



ARKANSAS

ENERGY & ENVIRONMENT

8/24/2022

Mr. Jason Johnson
American Electric Power
502 North Allen Avenue
Shreveport, LA 71101

RE: Inspection conducted on August 11, 2022
AFIN 29-00506
Permit Number 0311-S3N-R1

Dear Mr. Johnson,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or greenwood@adeq.state.ar.us

Sincerely,

A handwritten signature in black ink that reads 'Matt Greenwood'.

Matt Greenwood
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 3 Landfill Inspection Form**

Site Name	SWEPCO Class 3 Landfill - John W. Turk , Jr. Power Plant	County	Hempstead	AFIN	29-00506
Facility Address	About 4 miles north of Fulton off Hwy 355	Phone #	903-831-1514	Permit #	0311-S3N-R1
Permittee Address	3711 Highway 355 South, Fulton, AR 71838	Email Address	Jrjohnson1@aep.com	PDS #	121501
Date	08/11/22	Entry Time	0930	Exit Time	1030

Operational Standards

Category 1

Regulation	Item Description	Comments
522(a)	Annual Compliance Inspection by Registered Professional Engineer	

Category 2


Regulation	Item Description	Comments
510(a)	Operations in Accordance with Permit Documents	
516(c)	Adequate All Weather Operational Roads	
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
510(b)	Operations by Licensed On-site Operator at all Times	
510(d)	Waste Spread and Compacted as Unloaded	
518	Surface Water Control	
517(a)(b)	Run-on/off Control System Present and Adequate	
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
510(n)	Leachate Leaks or Evidence of Leachate Seepage	
526	Survey Controls	
529	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
518	Cause Discharge/Leachate Discharge Leaving Landfill	
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/off Lined Area	

Records

Date of Last Annual Report	June 2022	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	Feb 2022	Previous Quarter Waste Received	20804.23

Operator Name & Number	Tim Choate, 003552 Jason Johnson, Plant Environmental Coordinator	Signature of Inspector	
Exit Interview Conducted with	Jason Johnson	Method	On-Site
		Date	08/11/22
		Time	1020