ARKANSAS
ENERGY & ENVIRONMENT

9/14/2022

Julian Lott
City of Camden Mayor
P. O. Box 278
Camden, AR 71701-0278

**RE: Inspection conducted on September 7, 2022**
**AFIN 52-00069**
**Permit Number 0255-S4**

Dear Mayor Lott:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq*.), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us.

Sincerely,

Gerry Eddy
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations

ARKANSAS
ENERGY & ENVIRONMENT

# Office of Land Resources
# Regulated Waste Operations
# Class 4 Landfill Inspection Form

| | | | | | |
|---|---|---|---|---|---|
| **Site Name** | City of Camden Class 4 Landfill | **County** | Ouachita | **AFIN** | 52-00069 |
| **Facility Address** | 2463 Country Club Road | **Phone #** | 870-837-5573 | **Permit #** | 0255-S4 |
| **Permittee Address** | P.O. Box 278 Camden, AR | **Email Address** | mayor@explorecamden.com | **PDS #** | 122728 |
| **Date** | 9/7/2022 | **Entry Time** | 0955 | **Exit Time** | 1104 |

## Operational Standards

### Category 1

| | Regulation | Item Description | Comments |
|---|---|---|---|
| | 617(a)(b) | Record Keeping Requirements Specified by Regulations | |
| | 607(j) | Adequate Provisions for Backup Equipment | |
| | 619 | Annual Compliance Inspection by Registered Professional Engineer | |
| | | | |

### Category 2

| | Regulation | Item Description | Comments |
|---|---|---|---|
| | 607(a) | Operations in Accordance with Permit Documents | |
| | 613(c) | Adequate All Weather Operational Roads | |
| | 607(c)(d) | Smallest Practical Area, Single Working Face | |
| | 607(b) | Operations by Licensed On-site Personnel at All Times | |
| | 607(g) | Litter Control Provisions Maintained | |
| | 622 | Survey Controls | |
| | 623 | Surface Water Controls | |
| | 607(h)(1) | Contouring Prevents Surface Water Flowing Into or Through Waste | |
| | 607(h)(2) | Surface Water Control Prevents Off-site Sediment Accumulation | |
| | 607(i)(o) | Adequate Maintenance of Intermediate/Final Cover Vegetation | |
| | 607(o) | Leachate Leaks or Evidence of Leachate Seepage | |
| | | | |

### Category 3

| | Regulation | Item Description | Comments |
|---|---|---|---|
| | 608 | Implementation of Hazardous Waste Exclusion Plan | |
| | 609(a) | Satisfactory Weekly or More Frequent Cover | |
| | 609(b) | Satisfactory Immediate Cover | |
| | 615 | Cause Discharge/Leachate Discharge Leaving Landfill | |
| | 607(o) | Erosion or Other Cover Defects Resulting in Exposed Refuse | |
| | 309(c ) | Overfill/Off Lined Area | |
| | | | |

### Records

| | | | |
|---|---|---|---|
| **Date of Last Annual Report** | 6/6/2022 | **Date of Last Quarterly Methane Monitoring** | N/A |
| **Date of Last Groundwater Monitoring Report** | N/A | **Previous Quarter Waste Received** | 55.16 Tons |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Operator Name & Number** | Hershel Frazier 002934<br>James Alford 003719<br>Joseph Gulley 004482 | **Signature of Inspector** | | |  | | |
| **Exit Interview Conducted with** | Hershel Frazier | **Method** | In Person | **Date** | 9/7/2022 | **Time** | 1104 |