ARKANSAS
ENERGY & ENVIRONMENT

11/10/2022

Mayor Kyle Osborne
401 W. Arch Ave.
Searcy, AR 72143

**RE: Inspection conducted on October 21, 2022**
**AFIN 73-00054**
**Permit Number 0031-STSW-R2**

Dear Mayor Osborne:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq*.), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6909 or darrell.norton@adeq.state.ar.us

Sincerely,

Darrell Norton
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations

ARKANSAS
ENERGY & ENVIRONMENT

# Office of Land Resources
# Regulated Waste Operations
# Transfer Station & Solid Waste Recovery Inspection Form

| | | | | | |
|---|---|---|---|---|---|
| **Site Name** | City of Searcy Transfer Station | **County** | White | **AFIN** | 73-00054 |
| **Facility Address** | 2012 Eastline Road, Searcy, AR 72143 | **Phone #** | 501-279-1001 | **Permit #** | 0031-STSW-R2 |
| **Permittee Address** | 401 West Arch Avenue, Searcy, AR 72143 | **Email Address** | Kyle.Osborne@cityofsearcy.org lcook@cityofsearcy.org | **PDS #** | 123415 |
| **Date** | 10/21/2022 | **Entry Time** | 1005 | **Exit Time** | 1035 |
| **Classification** | X **Transfer Station** | | **Waste Recovery** | | |

## Operational Standards

### Category 1

| | Regulation | Item Description | Comments |
|---|---|---|---|
| | **904(g)** | **Recoverable Solid Waste** | |
| | **904(i)** | **Signs** | |
| | **904(n)** | **Annual Reporting** | |
| | | | |

### Category 2


| | Regulation | Item Description | Comments |
|---|---|---|---|
| | **904(e)** | **Storage Area** | |
| | **904(h)** | **Supervision of Facility** | . |
| | **904(j)** | **Control of Litter, Insects, Odors, & Vectors** | |
| | **904(k)** | **Facility Maintenance** | |
| | **904(m)** | **Fire Protection** | |
| | **904(p)** | **Operating Plan** | |
| | **905(b)** | **Unloading and Loading Areas** | |
| | **905** | **Meets Design Requirements** | New damage observed to the interior and east side of the covered processing area. (Refer to Photo #2.) |

### Category 3

| | Regulation | Item Description | Comments |
|---|---|---|---|
| | **904(a)** | **Acceptable Waste** | |
| | **904(b)** | **Ultimate Disposal of Waste** | |
| | **904(d)** | **Processing Areas** | |
| | **904(f)** | **External Storage** | Operating plan indicates **two** external roll-offs approved. One roll off is designated for the City of Searcy customers, and the other is for White County residents. Roll-offs are to be emptied daily or tarped as outlined in the approved operating plan. Currently there are **three** roll offs are being utilized at the facility. Minor Permit modification submitted to address yearly tonnage and operating plan. |
| | **904(l)** | **Drainage** | |
| | | | |

### Records

| | | | |
|---|---|---|---|
| **Date of Last Annual Report** | 3/15/2022 | **Previous Month's Waste Received** | 3572.74 tons |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| **Operator Name & Number** | Sherry Free 003255 | **Signature of Inspector** | | |  | | | |
| **Exit Interview Conducted with** | Sherry Free/Todd Phillips | **Method** | In person/via phone | **Date** | 10/21/2022 | **Time** | 1030 | |

# Division of Environmental Quality
# Official Photograph Sheet

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Location** | City of Searcy TS (Sewer) | | | **Permit** | 0031-STSW-R2 | **AFIN** | 73-00054 |
| **Photographer** | Darrell Norton, Inspector | DN | | **Witness** | N/A | | |
| **Photo #** | 1 | **Of** | 2 | **Date** | 10/21/2022 | **Time** | 1011 |
| **Description** | A view of the roll-offs utilized for external storage. | | | | | | |



| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Location** | City of Searcy TS (Sewer) | | | **Permit** | 0031-STSW-R2 | **AFIN** | 73-00054 |
| **Photographer** | Darrell Norton, Inspector | DN | | **Witness** | N/A | | |
| **Photo #** | 2 | **Of** | 2 | **Date** | 10/21/2022 | **Time** | 1014 |
| **Description** | A view of the covered processing area, with damage to the structure visible. | | | | | | |

