ARKANSAS
ENERGY & ENVIRONMENT

2/10/2023

The Honorable Craig Jones
St. Francis County Judge
313 S. Izard, Suite 1
Forrest City, AR 72335

RE: Inspection conducted on January 24, 2023
AFIN 62-00207
Permit Number 0121-STSW-C

Dear Judge Jones,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Tobin Baker. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 837-2097 or bakert@adeq.state.ar.us.

Sincerely,

Tobin Baker

Tobin Baker
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations

ARKANSAS
ENERGY & ENVIRONMENT

Office of Land Resources
Regulated Waste Operations
Transfer Station & Solid Waste Recovery Inspection Form

Site Name	St. Francis County Transfer Station	**County**	St. Francis	**AFIN**	62-00207
Facility Address	604 Martin Luther King Madison, AR 72359	**Phone #**	870-261-1700	**Permit #**	0121-STSW-C
Permittee Address	313 S. Izard Forrest City, AR 72335	**Email Address**	craig.jones@sfcar.us	**PDS #**	124548
Date	1/24/2023	**Entry Time**	1244	**Exit Time**	1315
Classification	X **Transfer Station**		**Waste Recovery**		

Operational Standards

Category 1

	Regulation	Item Description	Comments
	904(g)	Recoverable Solid Waste	
	904(i)	Signs	
	904(n)	Annual Reporting	

Category 2

	Regulation	Item Description	Comments
	904(e)	Storage Area	
	904(h)	Supervision of Facility	
X	904(j)	Control of Litter, Insects, Odors, & Vectors	Solid waste observed around the transfer station. (Refer to Photos #1 - #3.)
	904(k)	Facility Maintenance	
	904(m)	Fire Protection	
	904(p)	Operating Plan	
	905(b)	Unloading and Loading Areas	

Category 3

	Regulation	Item Description	Comments
	904(a)	Acceptable Waste	
	904(b)	Ultimate Disposal of Waste	
	904(d)	Processing Areas	
	904(f)	External Storage	
X	904(l)	Drainage	Standing leachate observed not draining to the sanitary sewer. (Refer to Photo #3.)

Records

Date of Last Annual Report	2/14/2022	**Previous Month's Waste Received**		51.26 tons	
Operator Name & Number	Jason Thetford 004121 Shane Gracey 004123 Scotty Jackson 004122	**Signature of Inspector**		Tobin Baker	
Exit Interview Conducted with	Shane Gracey	**Method**	On-site	**Date** 1/24/2023	**Time** 1310

Division of Environmental Quality
Official Photograph Sheet

Location	St. Francis County Transfer Station			**Permit**	0121-STSW-C	**AFIN**	62-00207
Photographer	Tobin Baker, Inspector TB			**Witness**	N/A		
Photo #	1	**Of**	3	**Date**	1/24/2023	**Time**	1250
Description	Solid waste observed around the transfer station.						



Location	St. Francis County Transfer Station			**Permit**	0121-STSW-C	**AFIN**	62-00207
Photographer	Tobin Baker, Inspector TB			**Witness**	N/A		
Photo #	2	**Of**	3	**Date**	1/24/2023	**Time**	1102
Description	Solid waste observed around the transfer station.						



Division of Environmental Quality
Official Photograph Sheet

Location	St. Francis County Transfer Station			**Permit**	0121-STSW-C	**AFIN**	62-00207
Photographer	Tobin Baker, Inspector TB			**Witness**	N/A		
Photo #	3	**Of**	3	**Date**	1/24/2023	**Time**	1252
Description	Solid waste observed around the transfer station and standing leachate observed not draining to the sanitary sewer.						

