ARKANSAS
ENERGY & ENVIRONMENT

3/17/2023

Charlotte Young
City of Camden Mayor
P. O. Box 278
Camden, AR 71701-0278

RE: Inspection conducted on March 14, 2023
AFIN 52-00069
Permit Number 0255-S4

Dear Mayor Young:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq*.), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us.

Sincerely,

Gerry Eddy
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations

ARKANSAS
ENERGY & ENVIRONMENT

Office of Land Resources
Regulated Waste Operations
Class 4 Landfill Inspection Form

Site Name	City of Camden Class 4 Landfill	**County**	Ouachita	**AFIN**	52-00069
Facility Address	2463 Country Club Road	**Phone #**	870-837-5573	**Permit #**	0255-S4
Permittee Address	P.O. Box 278 Camden, AR	**Email Address**	mayor@explorecamden.com	**PDS #**	125019
Date	3/14/2023	**Entry Time**	0937	**Exit Time**	1035

Operational Standards

Category 1

	Regulation	Item Description	Comments
	617(a)(b)	Record Keeping Requirements Specified by Regulations	
	607(j)	Adequate Provisions for Backup Equipment	
	619	Annual Compliance Inspection by Registered Professional Engineer	

Category 2

	Regulation	Item Description	Comments
	607(a)	Operations in Accordance with Permit Documents	
	613(c)	Adequate All Weather Operational Roads	
	607(c)(d)	Smallest Practical Area, Single Working Face	
	607(b)	Operations by Licensed On-site Personnel at All Times	
	607(g)	Litter Control Provisions Maintained	
	622	Survey Controls	
	623	Surface Water Controls	
	607(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	607(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	607(i)(o)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	607(o)	Leachate Leaks or Evidence of Leachate Seepage	

Category 3

	Regulation	Item Description	Comments
	608	Implementation of Hazardous Waste Exclusion Plan	
	609(a)	Satisfactory Weekly or More Frequent Cover	
	609(b)	Satisfactory Immediate Cover	
	615	Cause Discharge/Leachate Discharge Leaving Landfill	
	607(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
	309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	6/6/2022	**Date of Last Quarterly Methane Monitoring**	N/A
Date of Last Groundwater Monitoring Report	N/A	**Previous Quarter Waste Received**	25.13 Tons

Operator Name & Number	Hershel Frazier 002934 James Alford 003719 Joseph Gulley 004482	**Signature of Inspector**					
Exit Interview Conducted with	James Alford and Hershel Frazier	**Method**	In Person	**Date**	3/14/2023	**Time**	1035