



# ARKANSAS

## ENERGY & ENVIRONMENT

5/24/2023

Mr. Jason Johnson  
American Electric Power  
502 North Allen Avenue  
Shreveport, LA 71101

**RE: Inspection conducted on May 10, 2023**  
**AFIN 29-00506**  
**Permit Number 0311-S3N-R1**

Dear Mr. Johnson,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or [matt.greenwood@adeq.state.ar.us](mailto:matt.greenwood@adeq.state.ar.us)

Sincerely,

A handwritten signature in black ink that reads 'Matt Greenwood'.

Matt Greenwood  
Solid Waste Inspector  
5301 Northshore Drive, North Little Rock, AR 72118-5317

cc: Nicholas Jones P.E., Senior Operations Manager, Office of Land Resources



**ARKANSAS**  
ENERGY & ENVIRONMENT

**Office of Land Resources  
Regulated Waste Operations  
Class 3 Landfill Inspection Form**

<b>Site Name</b>	SWEPCO Class 3 Landfill - John W. Turk, Jr. Power Plant	<b>County</b>	Hempstead	<b>AFIN</b>	29-00506
<b>Facility Address</b>	About 4 miles north of Fulton off Hwy 355	<b>Phone #</b>	903-831-1514	<b>Permit #</b>	0311-S3N-R1
<b>Permittee Address</b>	3711 Highway 355 South, Fulton, AR 71838	<b>Email Address</b>	<a href="mailto:Jrjohnson1@aep.com">Jrjohnson1@aep.com</a>	<b>PDS #</b>	125932
<b>Date</b>	05/10/23	<b>Entry Time</b>	0800	<b>Exit Time</b>	0920

**Operational Standards**

**Category 1**

<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
522(a)	Annual Compliance Inspection by Registered Professional Engineer	

**Category 2**


<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
510(a)	Operations in Accordance with Permit Documents	
516(c)	Adequate All Weather Operational Roads	
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
510(b)	Operations by Licensed On-site Operator at all Times	
510(d)	Waste Spread and Compacted as Unloaded	
518	Surface Water Control	
517(a)(b)	Run-on/off Control System Present and Adequate	
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
510(n)	Leachate Leaks or Evidence of Leachate Seepage	
526	Survey Controls	
529	Leachate Collection System	

**Category 3**

<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
518	Cause Discharge/Leachate Discharge Leaving Landfill	
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/off Lined Area	

**Records**

<b>Date of Last Annual Report</b>	June 2022	<b>Date of Last Quarterly Methane Monitoring</b>	N/A
<b>Date of Last Groundwater Monitoring Report</b>	March 2023	<b>Previous Quarter Waste Received</b>	27,087.69

<b>Operator Name &amp; Number</b>	Tim Choate, 003552 Jason Johnson, Plant Environmental Coordinator	<b>Signature of Inspector</b>	
<b>Exit Interview Conducted with</b>	Jason Johnson	<b>Method</b>	On-Site
		<b>Date</b>	05/10/23
		<b>Time</b>	0910