



**DIVISION OF
ENVIRONMENTAL QUALITY**

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

8/8/2023

Ms. Jennifer Halpain
Entergy White Bluff Plant
1100 White Bluff Road
Redfield, AR 72132

RE: Inspection conducted on August 2, 2023
AFIN 35-00110
Permit Number 0199-S3N-R3

Dear Ms. Halpain:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 529-2790 or Bobby.Gentry@arkansas.gov

Sincerely,

A handwritten signature in cursive script that reads 'Bobby Gentry'.

Bobby Gentry
Solid Waste Inspector

cc: Heath Cobb, Senior Compliance Manager, Regulated Waste Operations

**Office of Land Resources
Regulated Waste Operations
Class 3 Landfill Inspection Form**

Site Name	Entergy Class 3 Landfill	County	Jefferson	AFIN	35-00110
Facility Address	Hwy 365 North, Redfield, AR 72132	Phone #	HW 501-397-6262 501- 688- 7270 Jennifer	Permit #	0199-S3N-R3
Permittee Address	P.O. Box 126, Redfield, AR 72132	Email Address	jhalpai@entergy.com	PDS #	126940
Date	8-2-2023	Entry Time	1010	Exit Time	1100

Operational Standards

Category 1

Regulation	Item Description	Comments
522(a)	Annual Compliance Inspection by Registered Professional Engineer	

Category 2

Regulation	Item Description	Comments
510(a)	Operations in Accordance with Permit Documents	
516(c)	Adequate All Weather Operational Roads	
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
510(b)	Operations by Licensed On-site Operator at all Times	
510(d)	Waste Spread and Compacted as Unloaded	
518	Surface Water Control	
517(a)(b)	Run-on/off Control System Present and Adequate	
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
510(n)	Leachate Leaks or Evidence of Leachate Seepage	
526	Survey Controls	
529	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
518	Cause Discharge/Leachate Discharge Leaving Landfill	
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/off Lined Area	

Records

Date of Last Annual Report	March 2023	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	N/A	Previous Quarter Waste Received	16,524 tons

Operator Name & Number	Thomas Bombino Lic: 002136	Signature of Inspector	
Exit Interview Conducted with	Thomas Bombino Lic: 002136	Method	onsite
		Date	8-2-2023
		Time	1100