



**DIVISION OF
ENVIRONMENTAL QUALITY**

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

4/26/2024

Ms. Jennifer Halpain
Entergy White Bluff Plant
1100 White Bluff Road
Redfield, AR 72132

RE: Inspection conducted on April 15, 2024
AFIN 35-00110
Permit Number 0199-S3N-R3

Dear Ms. Halpain:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 529-2790 or Bobby.Gentry@arkansas.gov

Sincerely,

A handwritten signature in cursive script that reads 'Bobby Gentry'.

Bobby Gentry
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

**Office of Land Resources
Regulated Waste Operations
Class 3 Landfill Inspection Form**

Site Name	Entergy Class 3 Landfill	County	Jefferson	AFIN	35-00110
Facility Address	Hwy 365 North, Redfield, AR 72132	Phone #	HW 501-397-6262 501- 688- 7270 Jennifer	Permit #	0199-S3N-R3
Permittee Address	P.O. Box 126, Redfield, AR 72132	Email Address	jhalpai@entergy.com tobryan@entergy.com	PDS #	130124
Date	4-15-2024	Entry Time	1045	Exit Time	1145

Operational Standards

Category 1

	Regulation	Item Description	Comments
	522(a)	Annual Compliance Inspection by Registered Professional Engineer	

Category 2


	Regulation	Item Description	Comments
	510(a)	Operations in Accordance with Permit Documents	
	516(c)	Adequate All Weather Operational Roads	
	510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
	510(b)	Operations by Licensed On-site Operator at all Times	
	510(d)	Waste Spread and Compacted as Unloaded	
	518	Surface Water Control	
	517(a)(b)	Run-on/off Control System Present and Adequate	
	510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	510(n)	Leachate Leaks or Evidence of Leachate Seepage	
	526	Survey Controls	
	529	Leachate Collection System	

Category 3

	Regulation	Item Description	Comments
	512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
	518	Cause Discharge/Leachate Discharge Leaving Landfill	
	510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
	309(c)	Overfill/off Lined Area	

Records

Date of Last Annual Report	March 2023	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	N/A	Previous Quarter Waste Received	23,890 tons

Operator Name & Number	Thomas Bombino Lic: 002136	Signature of Inspector	
Exit Interview Conducted with	Thomas Bombino Lic: 002136	Method	onsite
		Date	4-15-2024
		Time	1130

