



**DIVISION OF
ENVIRONMENTAL
QUALITY**

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

October 16, 2024

Mr. Lee Tedford, Manager
Conway Corporation Tupelo Bayou WWTP
PO Box 99
Conway, AR 72033
Email Address: lee.tedford@conwaycorp.com

RE: Tupelo Bayou WWTP Inspection (Faulkner County) – PDS# 130914
AFIN: 23-01095 Permit No.: AR0051951 & ARR001527

Dear Mr. Tedford:

On June 27, 2024, I performed a Compliance Evaluation Inspection, Collection System Inspection, and Industrial Stormwater Inspection of the above referenced facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection report is enclosed for your records.

No violations were noted at the time of the inspection. Please refer to the inspection report for any comments. If I can be of any assistance, please contact me at travis.harmon@arkansas.gov or (501) 837-2070.

Sincerely,

A handwritten signature in cursive script that reads "Travis Harmon".

Travis Harmon
Inspector, Office of Water Quality

CC via email: trey.lieblong@conwaycorp.com

 ENVIRONMENTAL QUALITY	OFFICE OF WATER QUALITY INSPECTION REPORT		
	AFIN: 23-01095		PERMIT #: AR0051951
	DATE: 6/27/2024		
	COUNTY: 23 Faulkner	PDS #: 130914	MEDIA: WN
GPS LAT: 35.051667 LONG: -92.535326 LOCATION: General Area			
FACILITY INFORMATION		INSPECTION INFORMATION	
NAME: Tupelo Bayou WWTP LOCATION: 1405 Lollie Road CITY: Conway, AR 72034		FACILITY TYPE: 1 - Municipal INSPECTOR ID#: 34689 S - State FACILITY EVALUATION RATING: 5 - Satisfactory INSPECTION TYPE: Compliance Evaluation DATE(S): 6/27/2024 ENTRY TIME: 09:30 EXIT TIME: 12:30 PERMIT EFFECTIVE DATE: 7/1/2023 PERMIT EXPIRATION DATE: 6/30/2028	
RESPONSIBLE OFFICIAL			
NAME / TITLE: Mr. Lee Tedford / Manager COMPANY: Conway Corporation Tupelo Bayou WWTP MAILING ADDRESS: PO Box 99 CITY, STATE, ZIP: Conway AR 72033 PHONE & EXT: / FAX: 501-450-6000 / EMAIL: lee.tedford@conwaycorp.com CONTACTED DURING INSPECTION: No		FAYETTEVILLE SHALE RELATED: N FAYETTEVILLE SHALE VIOLATIONS: N INSPECTION PARTICIPANTS NAME/TITLE/PHONE/FAX/EMAIL/ETC.: Mr. Trey Lieblong/ Environmental Coordinator/ 501-548-3040/ trey.lieblong@conwaycorp.com	
AREA EVALUATIONS (S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)			
S	PERMIT	S	FLOW MEASUREMENT
S	RECORDS/REPORTS	N	LABORATORY
S	OPERATION & MAINTENANCE	S	EFFLUENT/RECEIVING WATER
S	SAMPLING	S	SLUDGE HANDLING/DISPOSAL
N	OTHER:	N	STORMWATER
		N	FACILITY SITE REVIEW
		N	SELF-MONITORING PROGRAM
		N	PRETREATMENT
SUMMARY OF FINDINGS			
I found no permit violations at the time of inspection.			

GENERAL COMMENTS

Introduction

I inspected on June 27, 2024. The inspection was scheduled and Mr. Trey Lieblong, Environmental Coordinator, represented the facility. The City of Conway operates the Tupelo Bayou WWTP which is designed to treat 16.0 MGD.

WWTP Inspection

Treatment consists of mechanical bar screens, grit removal, primary clarifiers, 4-cell aeration basin with anoxic zones, two primary digesters and one secondary digester, secondary clarifiers, and 4 channel UV disinfection with citric acid bath to clean bulbs. All systems of treatment were in operation and appeared well maintained at the time of inspection. The plant was operating a single primary clarifier, one cell of aeration, and a single secondary clarifier at the time of inspection due to low influent flow.

Records Review

I reviewed monthly Discharge Monitoring Reports (DMR) from June 2023 through May 2024. There were no reported exceedances during this time period. I also reviewed the April 2024 biomonitoring report for proper organisms, durations, and dilution series. The facility provided the spreadsheet for March 2024, which includes all daily flows and parameter analysis results for DMR averaging and loading calculations.

INSPECTOR'S SIGNATURE: 	Travis Harmon	DATE: 7/9/2024
SUPERVISOR'S SIGNATURE: 	Jason Bolenbaugh	DATE: 10/9/2024

SECTION A: PERMIT VERIFICATION	
PERMIT SATISFACTORILY ADDRESSES OBSERVATIONS	☒ S ☐ M ☐ U ☐ NA ☐ NE
DETAILS:	
1. CORRECT NAME AND MAILING ADDRESS OF PERMITTEE:	☒ Y ☐ N ☐ NA ☐ NE
2. NOTIFICATION GIVEN TO EPA/STATE OF NEW DIFFERENT OR INCREASED DISCHARGES:	☐ Y ☐ N ☒ NA ☐ NE
3. NUMBER AND LOCATION OF DISCHARGE POINTS AS DESCRIBED IN PERMIT:	☒ Y ☐ N ☐ NA ☐ NE
4. ALL DISCHARGES ARE PERMITTED:	☒ Y ☐ N ☐ NA ☐ NE
SECTION B: RECORDKEEPING AND REPORTING EVALUATION	
RECORDS AND REPORTS MAINTAINED AS REQUIRED BY PERMIT	☒ S ☐ M ☐ U ☐ NA ☐ NE
DETAILS: <u>Left lab records request. Will be reviewed by OWQ Enforcement Branch.</u>	
1. ANALYTICAL RESULTS CONSISTENT WITH DATA REPORTED ON DMRS:	☒ Y ☐ N ☐ NA ☐ NE
2. SAMPLING AND ANALYSES DATA ADEQUATE AND INCLUDE:	☒ S ☐ M ☐ U ☐ NA ☐ NE
a. DATES AND TIME(S) OF SAMPLING:	☐ Y ☐ N ☐ NA ☒ NE
b. EXACT LOCATION(S) OF SAMPLING:	☐ Y ☐ N ☐ NA ☒ NE
c. NAME OF INDIVIDUAL PERFORMING SAMPLING:	☐ Y ☐ N ☐ NA ☒ NE
d. ANALYTICAL METHODS AND TECHNIQUES:	☐ Y ☐ N ☐ NA ☒ NE
e. RESULTS OF CALIBRATIONS:	☐ Y ☐ N ☐ NA ☒ NE
f. RESULTS OF ANALYSES:	☐ Y ☐ N ☐ NA ☒ NE
g. DATES AND TIMES OF ANALYSES:	☐ Y ☐ N ☐ NA ☒ NE
h. NAME OF PERSON(S) PERFORMING ANALYSES:	☐ Y ☐ N ☐ NA ☒ NE
3. LABORATORY EQUIPMENT CALIBRATION AND MAINTENANCE RECORDS ADEQUATE:	☐ S ☐ M ☐ U ☐ NA ☒ NE
4. PLANT RECORDS INCLUDE SCHEDULES, DATES OF EQUIPMENT MAINTENANCE AND REPAIR:	☐ S ☐ M ☐ U ☐ NA ☒ NE
5. EFFLUENT LOADINGS CALCULATED USING DAILY EFFLUENT FLOW AND DAILY ANALYTICAL DATA:	☒ Y ☐ N ☐ NA ☐ NE
SECTION C: OPERATIONS AND MAINTENANCE	
TREATMENT FACILITY PROPERLY OPERATED AND MAINTAINED	☒ S ☐ M ☐ U ☐ NA ☐ NE
DETAILS:	
1. TREATMENT UNITS PROPERLY OPERATED:	☒ S ☐ M ☐ U ☐ NA ☐ NE
2. TREATMENT UNITS PROPERLY MAINTAINED:	☒ S ☐ M ☐ U ☐ NA ☐ NE
3. STANDBY POWER OR OTHER EQUIVALENT PROVIDED:	☒ S ☐ M ☐ U ☐ NA ☐ NE
4. ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:	☒ S ☐ M ☐ U ☐ NA ☐ NE
5. ALL NEEDED TREATMENT UNITS IN SERVICE:	☒ S ☐ M ☐ U ☐ NA ☐ NE
6. ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED:	☒ S ☐ M ☐ U ☐ NA ☐ NE
7. SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED:	☒ S ☐ M ☐ U ☐ NA ☐ NE
8. OPERATION AND MAINTENANCE MANUAL AVAILABLE:	☒ Y ☐ N ☐ NA ☐ NE
9. STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED:	☒ Y ☐ N ☐ NA ☐ NE
10. PROCEDURES FOR EMERGENCY TREATMENT CONTROL ESTABLISHED:	☒ Y ☐ N ☐ NA ☐ NE
11. HAVE BYPASSES/OVERFLOWS OCCURRED AT THE PLANT OR IN THE COLLECTION SYSTEM IN THE LAST YEAR:	☐ Y ☒ N ☐ NA ☐ NE
12. IF SO, HAS THE REGULATORY AGENCY BEEN NOTIFIED:	☐ Y ☐ N ☒ NA ☐ NE
13. HAS CORRECTIVE ACTION BEEN TAKEN TO PREVENT ADDITIONAL BYPASSES/OVERFLOWS:	☐ Y ☐ N ☒ NA ☐ NE
14. HAVE ANY HYDRAULIC OVERLOADS OCCURRED AT THE TREATMENT PLANT:	☐ Y ☒ N ☐ NA ☐ NE
15. IF SO, DID PERMIT VIOLATIONS OCCUR AS A RESULT:	☐ Y ☐ N ☒ NA ☐ NE

SECTION D: SAMPLING	
PERMITTEE SAMPLING MEETS PERMIT REQUIREMENTS	☐ S ☐ M ☐ U ☐ NA ☒ NE
DETAILS: <u>Left lab records request. Will be reviewed by OWQ Enforcement Branch.</u>	
1. SAMPLES TAKEN AT SITE(S) SPECIFIED IN PERMIT:	☒ Y ☐ N ☐ NA ☐ NE
2. LOCATIONS ADEQUATE FOR REPRESENTATIVE SAMPLES:	☐ Y ☐ N ☐ NA ☒ NE
3. FLOW PROPORTIONED SAMPLES OBTAINED WHEN REQUIRED BY PERMIT:	☐ Y ☐ N ☐ NA ☒ NE
4. SAMPLING AND ANALYSES COMPLETED ON PARAMETERS SPECIFIED IN PERMIT:	☒ Y ☐ N ☐ NA ☐ NE
5. SAMPLING AND ANALYSES PERFORMED AT FREQUENCY SPECIFIED IN PERMIT:	☒ Y ☐ N ☐ NA ☐ NE
6. SAMPLE COLLECTION PROCEDURES ADEQUATE:	☐ Y ☐ N ☐ NA ☒ NE
a. SAMPLES REFRIGERATED DURING COMPOSITING:	☒ Y ☐ N ☐ NA ☐ NE
b. PROPER PRESERVATION TECHNIQUES USED:	☐ Y ☐ N ☐ NA ☒ NE
c. CONTAINERS AND SAMPLE HOLDING TIMES CONFORM TO 40 CFR 136:	☐ Y ☐ N ☐ NA ☒ NE
7. IF MONITORING IS PERFORMED MORE OFTEN THAN REQUIRED ARE RESULTS REPORTED ON THE DMR:	☐ Y ☐ N ☒ NA ☐ NE
SECTION E: FLOW MEASUREMENT	
PERMITTEE FLOW MEASUREMENT MEETS PERMIT REQUIREMENTS	☒ S ☐ M ☐ U ☐ NA ☐ NE
DETAILS:	
1. PRIMARY FLOW MEASUREMENT DEVICE PROPERLY INSTALLED AND MAINTAINED:___ TYPE OF DEVICE: <u>Parshall Flume</u>	☒ Y ☐ N ☐ NA ☐ NE
2. FLOW MEASURED AT EACH OUTFALL AS REQUIRED:	☒ Y ☐ N ☐ NA ☐ NE
3. SECONDARY INSTRUMENTS (TOTALIZERS, RECORDERS, ETC.) PROPERLY OPERATED AND MAINTAINED:	☒ Y ☐ N ☐ NA ☐ NE
4. CALIBRATION FREQUENCY ADEQUATE:	☒ Y ☐ N ☐ NA ☐ NE
5. RECORDS MAINTAINED OF CALIBRATION PROCEDURES:	☒ Y ☐ N ☐ NA ☐ NE
6. CALIBRATION CHECKS DONE TO ASSURE CONTINUED COMPLIANCE:	☒ Y ☐ N ☐ NA ☐ NE
7. FLOW ENTERING DEVICE WELL DISTRIBUTED ACROSS THE CHANNEL AND FREE OF TURBULENCE:	☒ Y ☐ N ☐ NA ☐ NE
8. FLOW MEASUREMENT EQUIPMENT ADEQUATE TO HANDLE EXPECTED RANGE OF FLOW RATES:	☒ Y ☐ N ☐ NA ☐ NE
9. HEAD MEASURED AT PROPER LOCATION:	☒ Y ☐ N ☐ NA ☐ NE
SECTION F: LABORATORY	
PERMITTEE LABORATORY PROCEDURES MEET PERMIT REQUIREMENTS	☐ S ☐ M ☐ U ☐ NA ☒ NE
DETAILS: <u>Left lab records request. Will be reviewed by OWQ Enforcement Branch.</u>	
1. EPA APPROVED ANALYTICAL PROCEDURES USED (40 CFR 136.3 FOR LIQUIDS, 503.8(B) FOR SLUDGES) :	☐ Y ☐ N ☐ NA ☒ NE
2. IF ALTERNATIVE ANALYTICAL PROCEDURES ARE USED, PROPER APPROVAL HAS BEEN OBTAINED:	☐ Y ☐ N ☐ NA ☒ NE
3. SATISFACTORY CALIBRATION AND MAINTENANCE OF INSTRUMENTS AND EQUIPMENT:	☐ Y ☐ N ☐ NA ☒ NE
4. QUALITY CONTROL PROCEDURES ADEQUATE:	☐ Y ☐ N ☐ NA ☒ NE
5. DUPLICATE SAMPLES ARE ANALYZED $\geq 10\%$ OF THE TIME:	☐ Y ☐ N ☐ NA ☒ NE
6. SPIKED SAMPLES ARE ANALYZED $\geq 10\%$ OF THE TIME:	☐ Y ☐ N ☐ NA ☒ NE
7. COMMERCIAL LABORATORY USED:	☐ Y ☒ N ☐ NA ☐ NE
a. LAB NAME:	
b. LAB ADDRESS:	
c. PARAMETERS PERFORMED:	
8. BIOMONITORING PROCEDURES ADEQUATE:	☒ Y ☐ N ☐ NA ☐ NE
a. PROPER ORGANISMS USED:	☒ Y ☐ N ☐ NA ☐ NE
b. PROPER DILUTION SERIES FOLLOWED:	☒ Y ☐ N ☐ NA ☐ NE
c. PROPER TEST METHODS AND DURATION:	☒ Y ☐ N ☐ NA ☐ NE
d. RETESTS AND/OR TRE PERFORMED AS REQUIRED:	☐ Y ☐ N ☒ NA ☐ NE

SECTION G: EFFLUENT/RECEIVING WATERS OBSERVATIONS							
BASED ON VISUAL OBSERVATIONS ONLY						☒ S ☐ M ☐ U ☐ NA ☐ NE	
DETAILS: <u>Composite sampler</u>							
OUTFALL #:	OIL SHEEN	GREASE	TURBIDITY	VISIBLE FOAM	FLOATING SOLIDS	COLOR	OTHER
001	none	none	none	none	none	clear	--
SECTION H: SLUDGE DISPOSAL							
SLUDGE DISPOSAL MEETS PERMIT REQUIREMENTS						☒ S ☐ M ☐ U ☐ NA ☐ NE	
DETAILS:							
1. SLUDGE MANAGEMENT ADEQUATE TO MAINTAIN EFFLUENT QUALITY:						☒ S ☐ M ☐ U ☐ NA ☐ NE	
2. SLUDGE RECORDS MAINTAINED AS REQUIRED BY 40 CFR 503:						☐ S ☐ M ☐ U ☐ NA ☒ NE	
3. FOR LAND APPLIED SLUDGE, TYPE OF LAND APPLIED TO: (E.G., FOREST, AGRICULTURAL, PUBLIC CONTACT SITE): <u>Agricultural</u>							
SECTION I: SAMPLING INSPECTION PROCEDURES							
SAMPLE RESULTS WITHIN PERMIT REQUIREMENTS						☐ S ☐ M ☐ U ☒ NA ☐ NE	
DETAILS:							
1. SAMPLES OBTAINED THIS INSPECTION:						☐ Y ☐ N ☒ NA ☐ NE	
2. TYPE OF SAMPLE: ☐ GRAB:___ ☐ COMPOSITE:___ METHOD:___ FREQUENCY:___							
3. SAMPLES PRESERVED:						☐ Y ☐ N ☒ NA ☐ NE	
4. FLOW PROPORTIONED SAMPLES OBTAINED:						☐ Y ☐ N ☒ NA ☐ NE	
5. SAMPLE OBTAINED FROM FACILITY'S SAMPLING DEVICE:						☐ Y ☐ N ☒ NA ☐ NE	
6. SAMPLE REPRESENTATIVE OF VOLUME AND NATURE OF DISCHARGE:						☐ Y ☐ N ☒ NA ☐ NE	
7. SAMPLE SPLIT WITH PERMITTEE:						☐ Y ☐ N ☒ NA ☐ NE	
8. CHAIN-OF-CUSTODY PROCEDURES EMPLOYED:						☐ Y ☐ N ☒ NA ☐ NE	
9. SAMPLES COLLECTED IN ACCORDANCE WITH PERMIT:						☐ Y ☐ N ☒ NA ☐ NE	
SECTION J: STORM WATER POLLUTION PREVENTION PLAN							
STORM WATER MANAGEMENT MEETS PERMIT REQUIREMENTS						☒ S ☐ M ☐ U ☐ NA ☐ NE	
DETAILS: <u>No violations of the No Exposure Exclusion- Permit #ARR001527</u>							
1. SWPPP UPDATED AS NEEDED:___ DATE OF LAST UPDATE:___						☐ Y ☐ N ☒ NA ☐ NE	
2. SITE MAP INCLUDING ALL DISCHARGES AND SURFACE WATERS:						☐ Y ☐ N ☒ NA ☐ NE	
3. POLLUTION PREVENTION TEAM IDENTIFIED:						☐ Y ☐ N ☒ NA ☐ NE	
4. POLLUTION PREVENTION TEAM PROPERLY TRAINED:						☐ Y ☐ N ☒ NA ☐ NE	
5. LIST OF POTENTIAL POLLUTANT SOURCES:						☐ Y ☐ N ☒ NA ☐ NE	
6. LIST OF POTENTIAL SOURCES AND PAST SPILLS AND LEAKS:						☐ Y ☐ N ☒ NA ☐ NE	
7. ALL NON-STORM WATER DISCHARGES ARE AUTHORIZED:						☐ Y ☐ N ☒ NA ☐ NE	
8. LIST OF STRUCTURAL BMPS:						☐ Y ☐ N ☒ NA ☐ NE	
9. LIST OF NON-STRUCTURAL BMPS:						☐ Y ☐ N ☒ NA ☐ NE	
10. BMPS PROPERLY OPERATED AND MAINTAINED:						☐ Y ☐ N ☒ NA ☐ NE	
11. INSPECTIONS CONDUCTED AS REQUIRED:						☐ Y ☐ N ☒ NA ☐ NE	

DMR Calculation Check

Reporting Period:	From	<u>2024</u>	<u>03</u>	<u>01</u>	To	<u>2024</u>	<u>03</u>	<u>31</u>
		Year	Month	Day		Year	Month	Day

Parameter Checked: TSS

	Loading Mass	Concentration	
	Mo. Avg. - lbs/day	Mo. Avg. - mg/l	7-day Avg. - mg/l
Reported Value:	<u>491.5</u>	<u>7.4</u>	<u>10.6</u>
Calculated Value:	<u>491.5</u>	<u>7.35</u>	<u>10.6</u>
Permit Value:	4003.2	30.0	45.0

If calculated value does not equal reported value, explain:

DMR Calculation Check

Reporting Period:	From	<u>2024</u>	<u>030</u>	<u>01</u>	To	<u>2024</u>	<u>03</u>	<u>31</u>
		Year	Month	Day		Year	Month	Day

Parameter Checked: BOD5

	Loading Mass	Concentration	
		Monthly	
	Mo. Avg. - lbs/day	Mo. Avg. - mg/l	7-day Avg. - mg/l
Reported Value:	<u>1007.1</u>	<u>16</u>	<u>19</u>
Calculated Value:	<u>1007.1</u>	<u>16.2</u>	<u>19</u>
Permit Value:	4003.2	30	45

If calculated value does not equal reported value, explain:

Office of Water Quality Photographic Evidence Sheet					
Location:	Tupelo Bayou WWTP				
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	0942
Witness:	None- no other regulatory personnel			Photo #:	1
Description:	Mechanical bar screens				
					
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	0943
Witness:	None			Photo #:	2
Description:	Additional view				
					

Office of Water Quality Photographic Evidence Sheet					
Location:	Tupelo Bayou WWTP				
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	0944
Witness:	None			Photo #:	3
Description:	Grit removal				
					
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	0945
Witness:	None			Photo #:	4
Description:	Waste bin				
					

Office of Water Quality Photographic Evidence Sheet					
Location:	Tupelo Bayou WWTP				
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	
Witness:	None			Photo #:	5
Description:	Primary clarifiers				
					
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	0949
Witness:	None			Photo #:	6
Description:	View of weir. One in service due to low influent.				
					

Office of Water Quality Photographic Evidence Sheet					
Location:	Tupelo Bayou WWTP				
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	0953
Witness:	None			Photo #:	7
Description:	4 cell aeration basin. One cell in service due to low flow.				
					
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	0954
Witness:	None			Photo #:	8
Description:	Anoxic zone				
					

Office of Water Quality Photographic Evidence Sheet			
Location:	Tupelo Bayou WWTP		
Photographer:	Travis Harmon	Date:	June 27, 2024
Witness:	None	Time:	0958
Description:	Sludge press		
			

Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	0959
Witness:	None			Photo #:	10
Description:	Polymer				

					
--	--	--	--	--	--

Office of Water Quality Photographic Evidence Sheet			
Location:	Tupelo Bayou WWTP		
Photographer:	Travis Harmon	Date:	June 27, 2024
Time:	1004	Witness:	None
Photo #:	11	Description:	Two primary digesters and one secondary digester
			

Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	1004
Witness:	None	Photo #:	12	Description:	Two primary digesters and one secondary digester
					

Office of Water Quality Photographic Evidence Sheet					
Location:	Tupelo Bayou WWTP				
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	1004
Witness:	None			Photo #:	13
Description:	Two primary digesters and one secondary digester				
					
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	1009
Witness:	None			Photo #:	14
Description:	Secondary clarifiers.				
					

Office of Water Quality Photographic Evidence Sheet			
Location:	Tupelo Bayou WWTP		
Photographer:	Travis Harmon	Date:	June 27, 2024
Witness:	None	Time:	1009
Description:	One in service due to low flow		
			

Photographer:	Travis Harmon	Date:	June 27, 2024
Witness:	None	Time:	1012
Description:	UV disinfection		
			


Office of Water Quality Photographic Evidence Sheet			
Location:	Tupelo Bayou WWTP		
Photographer:	Travis Harmon	Date:	June 27, 2024
Time:	1012		
Witness:	None		Photo #:
17			
Description:	UV disinfection		
			

Photographer:	Travis Harmon	Date:	June 27, 2024
Time:	1013		
Witness:	None		Photo #:
18			
Description:	UV bank panel		
			

Office of Water Quality Photographic Evidence Sheet					
Location:	Tupelo Bayou WWTP				
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	1015
Witness:	None			Photo #:	19
Description:	Effluent pumps when river is high. Gravity in normal river conditions.				
					
Photographer:	Travis Harmon	Date:	June 27, 2024	Time:	1016
Witness:	None			Photo #:	20
Description:	Composite sampler with view of final effluent in the container on the right.				
					

Office of Water Quality Photographic Evidence Sheet

Location:	Tupelo Bayou WWTP		
Photographer:	Travis Harmon	Date:	June 27, 2024
Witness:	None	Time:	1050
Description:	Plant operations monitoring		



Photographer:	Travis Harmon	Date:	June 27, 2024
Witness:	None	Time:	1050
Description:	Plant operations monitoring		



Google Earth (Portions are now enclosed inside buildings and image is prior):

