



ENVIRONMENTAL
QUALITY

OFFICE OF WATER QUALITY INSPECTION REPORT

AFIN: 58-00263 PERMIT #: DATE: 8/6/2024
COUNTY: 58 Pope PDS #: 131730 MEDIA: WN
GPS LAT: 35.2759 LONG: -93.0943 LOCATION: General Area

FACILITY INFORMATION

NAME:
Conagra Brands Industrial User of Russellville City Corp
LOCATION:
3100 E. Main St.
CITY:
Russellville

RESPONSIBLE OFFICIAL

NAME: / TITLE
Matt Fleetwood / EHS Specialist
COMPANY:
Conagra
MAILING ADDRESS:
3100 E. Main St.
CITY, STATE, ZIP:
Russellville AR 72811
PHONE & EXT: / FAX:
479-774-1793 /
EMAIL:
steven.fleetwood@conagra.com
CONTACTED DURING INSPECTION: **Yes**

INSPECTION INFORMATION

FACILITY TYPE: **1 - Municipal** INSPECTOR ID#: **36537 S - State**
FACILITY EVALUATION RATING: **3 - Satisfactory** INSPECTION TYPE: **Industrial User**
DATE(S): **8/6/2024** ENTRY TIME: **12:15** EXIT TIME: **13:10** PERMIT EFFECTIVE DATE:
PERMIT EXPIRATION DATE:

FAYETTEVILLE SHALE RELATED: **N**

FAYETTEVILLE SHALE VIOLATIONS: **N**

INSPECTION PARTICIPANTS

NAME/TITLE/PHONE/FAX/EMAIL/ETC.:
Thomas Jones, Conagra Maintenance Supervisor, 479-498-7574, thomas.jones@conagra.com;
Michael B. Hall, City Corp Pretreatment Coordinator, mhall@citycorporation.com;
Gracie Morrison, OWQ Water Quality Specialist

AREA EVALUATIONS

(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)


**	PERMIT	**	FLOW MEASUREMENT	**	STORMWATER
**	RECORDS/REPORTS	**	LABORATORY	**	FACILITY SITE REVIEW
**	OPERATION & MAINTENANCE	**	EFFLUENT/RECEIVING WATER	**	SELF-MONITORING PROGRAM
**	SAMPLING	**	SLUDGE HANDLING/DISPOSAL	**	PRETREATMENT
S	OTHER: IU inspection				

SUMMARY OF FINDINGS

No violations were noted during the inspection.

GENERAL COMMENTS

This inspection was conducted in conjunction with Russellville City Corp Pretreatment Compliance Inspection (PDS# 131594) for 2024.

INSPECTOR'S SIGNATURE:  **Amy Huneycutt**

DATE: **8/28/2024**

SUPERVISOR'S SIGNATURE:  **Jason Bolenbaugh**

DATE: **9/12/2024**

Industrial Site Visit

Name of Industry: Conagra Brands – Russellville

Industry Contacts: Thomas Jones, Matt Fleetwood

Type of Industry: Food processing

Date of Visit: August 6, 2024

- | | | | | |
|-----|--|---|--|---|
| 1. | Significant industrial user: | ☒ Yes | ☐ No | ☐ N/A |
| 2. | Pretreatment equipment or procedures? | ☒ Yes | ☐ No | ☐ N/A |
| 3. | Pretreatment equipment maintained and operational? | ☒ Yes | ☐ No | ☐ N/A |
| 4. | Hazardous waste generated or stored? | ☐ Yes | ☒ No | ☐ N/A |
| 5. | Proper solid waste disposal? | ☒ Yes | ☐ No | ☐ N/A |
| 6. | Solvent management/TTO control? | ☐ Yes | ☐ No | ☒ N/A |
| 7. | Suitable sampling location? | ☒ Yes | ☐ No | ☐ N/A |
| 8. | Appropriate self-monitoring procedures/equipment? | ☒ Yes | ☐ No | ☐ N/A |
| 9. | Adequate spill prevention? | ☒ Yes | ☐ No | ☐ N/A |
| 10. | Industry familiar with limits and requirements? | ☒ Yes | ☐ No | ☐ N/A |

Additional Comments: This facility produces frozen meals and bagged meals. They cook chicken, noodles, and sauces. Wastewater comes from dewatering chicken and sanitation. The treatment system consists of bar screen, rotor screen, EQ basin 1 with pH adjustment, DAF1, EQ basin 2, flocculation tank (add polymer, coagulant, and caustic), DAF2, then discharge to collection system. Organic solids are disposed by a contract company (Denali), inorganic solids are disposed in the trash.

Office of Water Quality Photographic Evidence Sheet

Location:	Conagra Brands Industrial User of Russellville City Corp		
Photographer:	Amy Huneycutt	Date:	August 6, 2024
Witness:	Gracie Morrison	Time:	1250
Description:	Pretreatment bar screen		



Photographer:	Amy Huneycutt	Date:	August 6, 2024
Witness:	Gracie Morrison	Time:	1252
Description:	Equalization basin		



Office of Water Quality Photographic Evidence Sheet

Location:	Conagra Brands Industrial User of Russellville City Corp				
Photographer:	Amy Huneycutt	Date:	August 6, 2024	Time:	1257
Witness:	Gracie Morrison			Photo #:	3
Description:	DAF 1				



Photographer:	Amy Huneycutt	Date:	August 6, 2024	Time:	1257
Witness:	Gracie Morrison			Photo #:	4
Description:	Floc tank				



Office of Water Quality Photographic Evidence Sheet

Location:	Conagra Brands Industrial User of Russellville City Corp				
Photographer:	Amy Huneycutt	Date:	August 6, 2024	Time:	1259
Witness:	Gracie Morrison			Photo #:	5
Description:	DAF 2				



Photographer:	Amy Huneycutt	Date:	August 6, 2024	Time:	1301
Witness:	Gracie Morrison			Photo #:	6
Description:	Treated water discharged to City Corp				

