



DIVISION OF
ENVIRONMENTAL QUALITY

133931

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

08/12/2025

Mr. Jason Johnson
American Electric Power
502 North Allen Avenue
Shreveport, LA 71101

RE: Inspection conducted on July 31, 2025
AFIN 29-00506
Permit Number 0311-S3N-R1

Dear Mr. Johnson,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6915 or matthew.greenwood@arkansas.gov.

Sincerely,

A handwritten signature in cursive script that reads "Matt Greenwood".

Matt Greenwood
Solid Waste Inspector

cc: Ryan Hayden, Compliance Program Manager, Regulated Waste Operations

Division of Environmental Quality - Office of Land Resources
Class 3 Landfill Inspection Form

Site Name	SWEPCO Class 3 Landfill - John W. Turk, Jr. Power Plant	County	Hempstead	AFIN	29-00506
Facility Address	About 4 miles north of Fulton off Hwy 355	Phone #	903-831-1514	Permit #	0311-S3N-R1
Permittee Address	3711 Highway 355 South, Fulton, AR 71838	Email Address	Jrjohnson1@aep.com	PDS #	133931
Date	07/31/25	Entry Time	0830	Exit Time	1000

Operational Standards

Category 1

Citation	Description	Comments
8 CAR § 60-522	Annual Engineering Inspection Report	

Category 2


Citation	Description	Comments
8 CAR § 60-510(a)	Operations in Accordance with Permit Documents	
8 CAR § 60-516(c)	Access and Operational Roads	
8 CAR § 60-510(c)	Working Face	
8 CAR § 60-510(b)	Operations by Licensed On-site Operator at all Times	
8 CAR § 60-510(d)	Waste Spread and Compacted as Unloaded	
8 CAR § 60-518	Surface Water Control	
8 CAR § 60-517	Run-On/Run-Off Control System Present and Adequate	
8 CAR § 60-510(h)(2)(A)	Surface Water Control Prevents Off-site Sediment Accumulation	
8 CAR § 60-510(i)	Final Cover Vegetation and Maintenance	
8 CAR § 60-510(n)(2)	Leachate Leaks or Evidence of Leachate Seepage	
8 CAR § 60-526	Survey Controls	
8 CAR § 60-529	Leachate Collection System	

Category 3

Citation	Description	Comments
8 CAR § 60-512	Satisfactory Daily/Intermediate/Alternative Cover	
8 CAR § 60-518(a)(5)	Allow Leachate unpermitted by NPDES to Leave Landfill	
8 CAR § 60-510(n)(1)	Erosion or Other Cover Defects Resulting in Exposed Waste	
8 CAR § 60-309(c)	Overfill / Off Lined Area	

Records

Date of Last Annual Report	06/26/24	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	07/10/25	Previous Quarter Waste Received	26,972 Tons

Operator Name & Number	Tim Choate, 003552 Jason Johnson, Plant Environmental Coordinator	Signature of Inspector	
Exit Interview Conducted with	Jason Johnson	Method	On-Site
		Date	07/31/25
		Time	0950