DIVISION OF
ENVIRONMENTAL QUALITY

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

9/19/2025

Anna Grace Foreman
Blackstone Construction
444 Hedgepath Rd
Russellville AR, 72802

RE: Inspection conducted on August 27, 2025
AFIN 53-00029
Permit Number 0264-S

Dear Ms. Foreman,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq*.), of 1971, as amended, the Arkansas Pollution Control & Ecology Rule, codified as 8 CAR § 60 (Solid Waste Management Rules), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Daniel Cullum. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 258-3144 or daniel.cullum@arkansas.gov.

Sincerely,

Daniel Cullum

Daniel Cullum
Solid Waste Inspector

cc: Ryan Hayden, Compliance Program Manager, Office of Land Resources

Division of Environmental Quality - Office of Land Resources
Class 4 Landfill Inspection Form

Site Name	Perry County Class 4 Landfill (Blackstone Construction)	**County**	Perry	**AFIN**	53-00029
Facility Address	115 Casa Aplin Rd, Casa, AR	**Phone #**	870-0405-5885, Anna	**Permit #**	0264-S
Permittee Address	444 Hedgepath Rd Russellville AR, 72802	**Email Address**	aforeman@bscasphalt.com	**PDS #**	134075
Date	08/27/2025	**Entry Time**	1015	**Exit Time**	1058

Operational Standards

Category 1

	Citation	Description	Comments
	8 CAR § 60-617( )	Record Keeping Requirements	
	8 CAR § 60-607(j)( )	Adequate Provisions for Backup Equipment	
	8 CAR § 60-619( )	Annual Engineering Inspection Report	

Category 2

	Citation	Description	Comments
	8 CAR § 60-607(a)	Operations in Accordance with Permit Documents	
	8 CAR § 60-613(c)( )	Access and Operational Roads	
	8 CAR § 60-607(c)( )	Working Face	
	8 CAR § 60-607(b)	Operations by Licensed On-site Operator at All Times	
	8 CAR § 60-607(g)	Litter Control	
	8 CAR § 60-622	Survey Controls	
	8 CAR § 60-623	Surface Water Controls	
	8 CAR § 60-607(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Working Face	
	8 CAR § 60-607(h)(2)(A)	Surface Water Control Prevents Off-site Sediment Accumulation	
	8 CAR § 60-607(i)( )	Final Cover Vegetation and Maintenance	
	8 CAR § 60-607(o)(2)	Leachate Leaks or Evidence of Leachate Seepage	
	Note	**Permit Name Change**	Request for permit name change was submitted to ADEQ 06/25/2025.

Category 3

	Citation	Description	Comments
	6088 CAR § 60-608( )	Exclude Receipt of Hazardous and Unauthorized Wastes	
	8 CAR § 60-609(a)( )	Satisfactory Weekly or More Frequent Cover	
	8 CAR § 60-609(b)	Satisfactory Intermediate Cover	
	8 CAR § 60-615(a)(5)	Allow Leachate Unpermitted by NPDES to Leave the Landfill	
X	**8 CAR § 60-607(o)(1)**	Erosion or Other Cover Defects Resulting in Exposed Refuse	Exposed waste was observed on the south slope of the landfill. (Refer to Photos #1 - #4.)
	8 CAR § 60-309(c)	Overfill / Off Lined Area	

Records

Date of Last Annual Report	07/31/2025	**Date of Last Quarterly Methane Monitoring**	NA
Date of Last Groundwater Monitoring Report	NA	**Previous Quarter Waste Received**	No waste taken

Operator Name & Number	Not in Operation	**Signature of Inspector**						
Exit Interview Conducted with	Anna Foreman	**Method**	Via Phone	**Date**	09/10/2025	**Time**	1506	

Division of Environmental Quality
Official Photograph Sheet

Location	Perry County Class 4 Landfill (Blackstone Construction)			**Permit**	0264-S	**AFIN**	53-00029
Photographer	Daniel Cullum DC			**Witness**	NA		
Photo #	1	**of**	4	**Date**	08/27/2025	**Time**	1038
Description	Exposed waste was observed on the south slope.						



Location	Perry County Class 4 Landfill (Blackstone Construction)			**Permit**	0264-S	**AFIN**	53-00029
Photographer	Daniel Cullum DC			**Witness**	NA		
Photo #	2	**of**	4	**Date**	08/27/2025	**Time**	1038
Description	Exposed waste was observed on the south slope.						



Division of Environmental Quality
Official Photograph Sheet

Location	Perry County Class 4 Landfill (Blackstone Construction)			**Permit**	0264-S	**AFIN**	53-00029
Photographer	Daniel Cullum DC			**Witness**	NA		
Photo #	3 **of** 4			**Date**	08/27/2025	**Time**	1038
Description	Exposed waste was observed on the south slope.						



Location	Perry County Class 4 Landfill (Blackstone Construction)			**Permit**	0264-S	**AFIN**	53-00029
Photographer	Daniel Cullum DC			**Witness**	NA		
Photo #	4 **of** 4			**Date**	08/27/2025	**Time**	1038
Description	Exposed waste was observed on the south slope.						

