



**DIVISION OF
ENVIRONMENTAL QUALITY**

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

Via Email: jhalpai@entergy.com
tobryan@entergy.com

12/16/2025

Ms. Jennifer Halpain
Entergy White Bluff Plant
1100 White Bluff Road
Redfield, AR 72132

RE: Inspection conducted on December 15, 2025
AFIN 35-00110
Permit Number 0199-S3N-R3

Dear Ms. Halpain,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-0832 or casey.jackson@arkansas.gov.

Sincerely,

A handwritten signature in black ink, appearing to read 'Casey J. Jackson'.

Casey Jackson
Solid Waste Inspector

cc: Ryan Hayden, Compliance Program Manager, Office of Land Resources

Division of Environmental Quality - Office of Land Resources
Class 3 Landfill Inspection Form

Site Name	Entergy	County	Jefferson	AFIN	35-00110
Facility Address	HWY 365 North Redfield, AR 72132	Phone #	HW 501-397-6262	Permit #	0199-S3N-R3
Permittee Address	P.O. Box 126, Redfield, AR 72132	Email Address	jhalpai@entergy.com tobryan@entergy.com	PDS #	134251
Date	12/56/2025	Entry Time	1107	Exit Time	1133

Operational Standards

Category 1

Citation	Description	Comments
8 CAR § 60-522	Annual Engineering Inspection Report	

Category 2

Citation	Description	Comments
8 CAR § 60-510(a)	Operations in Accordance with Permit Documents	
8 CAR § 60-516(c)	Access and Operational Roads	
8 CAR § 60-510(c)	Working Face	
8 CAR § 60-510(b)	Operations by Licensed On-site Operator at all Times	
8 CAR § 60-510(d)	Waste Spread and Compacted as Unloaded	
8 CAR § 60-518	Surface Water Control	
8 CAR § 60-517	Run-On/Run-Off Control System Present and Adequate	
8 CAR § 60-510(h)(2)(A)	Surface Water Control Prevents Off-site Sediment Accumulation	
8 CAR § 60-510(i)	Final Cover Vegetation and Maintenance	
8 CAR § 60-510(n)(2)	Leachate Leaks or Evidence of Leachate Seepage	
8 CAR § 60-526	Survey Controls	
8 CAR § 60-529	Leachate Collection System	

Category 3

Citation	Description	Comments
8 CAR § 60-512	Satisfactory Daily/Intermediate/Alternative Cover	
8 CAR § 60-518(a)(5)	Allow Leachate unpermitted by NPDES to Leave Landfill	
8 CAR § 60-510(n)(1)	Erosion or Other Cover Defects Resulting in Exposed Waste	
8 CAR § 60-309(c)	Overfill / Off Lined Area	

Records

Date of Last Annual Report	6/23/2025	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	N/A	Previous Quarter Waste Received	7463 Tons

Operator Name & Number	Thomas Bombino - 002136	Signature of Inspector	
Exit Interview Conducted with	Chris Langston	Method	On-Site
		Date	12/15/2025
		Time	1130