



**DIVISION OF
ENVIRONMENTAL QUALITY**

134517

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

Sent Via Email: jwesson@gbp.com

June 11, 2026

Mr. Jacob Wesson
Green Bay Packaging, Inc.
338 Hwy 113
Morrilton, AR 72110

RE: Inspection conducted on June 10, 2026
AFIN 15-00001
Permit Number 0284-S3N

Dear Mr. Wesson,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501)837-6909 or Darrell.norton@arkansas.gov.

Sincerely,

A handwritten signature in cursive script that reads "Darrell Norton".

Darrell Norton
Solid Waste Inspector

cc: Ryan Hayden, E&E Program Manager, Office of Land Resources

Division of Environmental Quality - Office of Land Resources
Class 3 Landfill Inspection Form

Site Name	Green Bay Packaging Inc.	County	Conway	AFIN	15-00001
Facility Address	338 Hwy 113 Morrilton, AR 72110	Phone #	501-354-9518	Permit #	0284-S3N
Permittee Address	338 Hwy 113 Morrilton, AR 72110	Email Address	jwesson@gbp.com	PDS #	134517
Date	6/10/2026	Entry Time	0910	Exit Time	1105

Operational Standards

Category 1

	Citation	Description	Comments
	8 CAR § 60-522(b)	Annual Engineering Inspection Report	

Category 2


	Citation	Description	Comments
	8 CAR § 60-510(a)	Operations in Accordance with Permit Documents	
	8 CAR § 60-516(c)	Access and Operational Roads	
	8 CAR § 60-510(c)	Working Face	
	8 CAR § 60-510(b)	Operations by Licensed On-site Operator at all Times	
	8 CAR § 60-510(d)	Waste Spread and Compacted as Unloaded	
	8 CAR § 60-518	Surface Water Control	
	8 CAR § 60-517	Run-On/Run-Off Control System Present and Adequate	
	8 CAR § 60-510(h)(2)(A)	Surface Water Control Prevents Off-site Sediment Accumulation	
	8 CAR § 60-510(i)	Final Cover Vegetation and Maintenance	
	8 CAR § 60-510(n)(2)	Leachate Leaks or Evidence of Leachate Seepage	
	8 CAR § 60-526	Survey Controls	Maintain survey controls in accordance with 8 CAR§ 60-426(f).
	8 CAR § 60-529	Leachate Collection System	

Category 3

	Citation	Description	Comments
	8 CAR § 60-512	Satisfactory Daily/Intermediate/Alternative Cover	
	8 CAR § 60-518(a)(5)	Allow Leachate unpermitted by NPDES to Leave Landfill	
	8 CAR § 60-510(n)(1)	Erosion or Other Cover Defects Resulting in Exposed Waste	
	8 CAR § 60-309(c)	Overfill / Off Lined Area	

Records

Date of Last Annual Report	3/23/2025	Date of Last Quarterly Methane Monitoring	n/a
Date of Last Groundwater Monitoring Report	10/30/2025	Previous Quarter Waste Received	71565 CY

Operator Name & Number	Jacob Wesson-004582	Signature of Inspector	
Exit Interview Conducted with	Jacob Wesson	Method	In-person
		Date	6/10/2026
		Time	1050

Arkansas Division of Environmental Quality

Official Photograph Sheet

Location	Green Bay Packaging				Permit	0284-S3N	AFIN	15-00001
Photographer	Darrell Norton, Inspector			<i>DN</i>	Witness	Jacob Wesson, Env. Manager		
Photo #	1	Of	4		Date	6/10/2026	Time	0949
Description	Newly constructed Area 6 as observed at the time of the inspection.							



Location	Green Bay Packaging				Permit	0284-S3N	AFIN	15-00001
Photographer	Darrell Norton, Inspector			<i>DN</i>	Witness	Jacob Wesson, Env. Manager		
Photo #	2	Of	4		Date	6/10/2026	Time	1002
Description	The working face as observed at the time of the inspection.							



Arkansas Division of Environmental Quality Official Photograph Sheet

Location	Green Bay Packaging			Permit	0284-S3N	AFIN	15-00001
Photographer	Darrell Norton, Inspector		<i>DW</i>	Witness	Jacob Wesson, Env. Manager		
Photo #	3	Of	4	Date	6/10/2026	Time	1009
Description	The east slope of Area 5 observed with additional intermediate cover recently applied.						



Location	Green Bay Packaging			Permit	0284-S3N	AFIN	15-00001
Photographer	Darrell Norton, Inspector		<i>DW</i>	Witness	Jacob Wesson, Env. Manager		
Photo #	4	Of	4	Date	6/10/2026	Time	1028
Description	The leachate sump and control panel for the collection system pump on the north side of Area 6.						

