DIVISION OF
ENVIRONMENTAL QUALITY

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

Via Email: dmahoney@garlandcounty.org

06/11/2026

The Honorable Darryl Mahoney
Garland County Judge
501 Ouachita, Suite B4
Hot Springs, AR 71901

**RE: Inspection conducted on June 03, 2026**
**AFIN 26-00405**
**Permit Number 0300-S4**

Dear Judge Mahoney,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq*.), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6915 or Matthew.Greenwood@arkansas.gov.

Sincerely,

Matthew Greenwood
Solid Waste Inspector

cc: Ryan Hayden, Compliance Program Manager, Office of Land Resources

# Division of Environmental Quality - Office of Land Resources
# Class 4 Landfill Inspection Form

| | | | | | |
|---|---|---|---|---|---|
| **Site Name** | Garland County Class 4 Landfill | **County** | Garland | **AFIN** | 26-00405 |
| **Facility Address** | 1040 Cedar Glades Rd, Hot Springs, AR | **Phone #** | 501-623-7499 | **Permit #** | 0300-S4 |
| **Permittee Address** | 501 Ouachita Ave., Suite 4-B, Hot Springs, AR | **Email Address** | dmahoney@garlandcounty.org | **PDS #** | 134520 |
| **Date** | 03/06/26 | **Entry Time** | 0900 | **Exit Time** | 1000 |

## Operational Standards

### Category 1

| | Citation | Description | Comments |
|---|---|---|---|
| | **8 CAR § 60-617** | Record Keeping Requirements | |
| | **8 CAR § 60-607(j)** | Adequate Provisions for Backup Equipment | |
| | **8 CAR § 60-619** | Annual Engineering Inspection Report | |

### Category 2


| | Citation | Description | Comments |
|---|---|---|---|
| | **8 CAR § 60-607(a)** | Operations in Accordance with Permit Documents | |
| | **8 CAR § 60-613(c)** | Access and Operational Roads | |
| | **8 CAR § 60-607(c)** | Working Face | |
| | **8 CAR § 60-607(b)** | Operations by Licensed On-site Operator at All Times | |
| | **8 CAR § 60-607(g)** | Litter Control | |
| | **8 CAR § 60-623** | Surface Water Controls | |
| | **8 CAR § 60-607(h)(1)** | Contouring Prevents Surface Water Flowing Into or Through Working Face | |
| | **8 CAR § 60-607(h)(2)(A)** | Surface Water Control Prevents Off-site Sediment Accumulation | |
| | **8 CAR § 60-607(i)** | Final Cover Vegetation and Maintenance | |
| | **8 CAR § 60-607(o)(2)** | Leachate Leaks or Evidence of Leachate Seepage | |

### Category 3

| | Citation | Description | Comments |
|---|---|---|---|
| | **6088 CAR § 60-608** | Exclude Receipt of Hazardous and Unauthorized Wastes | |
| | **8 CAR § 60-609(a)** | Satisfactory Weekly or More Frequent Cover | |
| | **8 CAR § 60-609(b)** | Satisfactory Intermediate Cover | |
| | **8 CAR § 60-615(a)(5)** | Allow Leachate Unpermitted by NPDES to Leave the Landfill | |
| | **8 CAR § 60-607(o)(1)** | Erosion or Other Cover Defects Resulting in Exposed Refuse | |
| | **8 CAR § 60-309(c)** | Overfill / Off Lined Area | |

### Records

| | | | |
|---|---|---|---|
| **Date of Last Annual Report** | 06/27/2025 | **Date of Last Quarterly Methane Monitoring** | NA |
| **Date of Last Groundwater Monitoring Report** | NA | **Previous Quarter Waste Received** | 9590.90 Tons |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Operator Name & Number** | Billy Sawyer 4316 | **Signature of Inspector** | | |  | | |
| **Exit Interview Conducted with** | Billy Sawyer | **Method** | On Site | **Date** | 06/03/26 | **Time** | 0955 |

# Division of Environmental Quality
# Official Photograph Sheet

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Location** | Garland Class 4 | | | **Permit** | 0300-S4 | **AFIN** | 26-00405 |
| **Photographer** | Matthew Greenwood | MG | | **Witness** | Billy Sawyer | | |
| **Photo #** | 1 | **of** | 1 | **Date** | 06/03/26 | **Time** | 0916 |
| **Description** | The working face was observed. | | | | | | |

