DIVISION OF
ENVIRONMENTAL QUALITY

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

Via Email: Christopher.Ayers@domtar.com

09/21/2026

Mr. Brandon Ayers
Domtar A. W. Corp.
285 Hwy. 71 South
Ashdown, AR 71822-0496

RE: Inspection conducted on September 03, 2026
AFIN 41-00002
Permit Number 0296-S3N

Dear Mr. Ayers:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq*.), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6915 or matthew.greenwood@arkansas.gov.

Sincerely,

Matthew Greenwood
Solid Waste Inspector

cc: Ryan Hayden, E&E Program Manager, Office of Land Resources

Division of Environmental Quality - Office of Land Resources
Class 3 Landfill Inspection Form

Site Name	Domtar A.W. LLC Lime	**County**	Little River	**AFIN**	41-00002
Facility Address	Hwy. 71 S. of Ashdown	**Phone #**	870-898-2711 Ext 6172	**Permit #**	0296-S3N
Permittee Address	285 Hwy. 71 South Ashdown, AR 71822-0496	**Email Address**	Christopher.Ayers@domtar.com	**PDS #**	134668
Date	09/03/26	**Entry Time**	0900	**Exit Time**	1030

Operational Standards

Category 1

	Citation	Description	Comments
	8 CAR § 60-522	Annual Engineering Inspection Report	

Category 2

	Citation	Description	Comments
	8 CAR § 60-510(a)	Operations in Accordance with Permit Documents	
	8 CAR § 60-516(c)	Access and Operational Roads	
	8 CAR § 60-510(c)	Working Face	
	8 CAR § 60-510(b)	Operations by Licensed On-site Operator at all Times	
	8 CAR § 60-510(d)	Waste Spread and Compacted as Unloaded	
	8 CAR § 60-518	Surface Water Control	
	8 CAR § 60-517	Run-On/Run-Off Control System Present and Adequate	
	8 CAR § 60-510(h)(2)(A)	Surface Water Control Prevents Off-site Sediment Accumulation	
	8 CAR § 60-510(i)	Final Cover Vegetation and Maintenance	
	8 CAR § 60-510(n)(2)	Leachate Leaks or Evidence of Leachate Seepage	
	8 CAR § 60-526	Survey Controls	
	8 CAR § 60-529	Leachate Collection System	

Category 3

	Citation	Description	Comments
	8 CAR § 60-512	Satisfactory Daily/Intermediate/Alternative Cover	
	8 CAR § 60-518(a)(5)	Allow Leachate unpermitted by NPDES to Leave Landfill	
	8 CAR § 60-510(n)(1)	Erosion or Other Cover Defects Resulting in Exposed Waste	
	8 CAR § 60-309(c)	Overfill / Off Lined Area	

Records

Date of Last Annual Report	06/19/26	**Date of Last Quarterly Methane Monitoring**	N/A
Date of Last Groundwater Monitoring Report	09/05/26	**Previous Quarter Waste Received**	96 Yrds

Operator Name & Number	Charles D. Schuetz 002943 Charles Allen	**Signature of Inspector**					
Exit Interview Conducted with	Charles Allen	**Method**	On-Site	**Date**	09/03/26	**Time**	1025

Division of Environmental Quality
Official Photograph Sheet

Location	Domtar Lime			**Permit**	0296-S3N	**AFIN**	41-00002
Photographer	Matt Greenwood MG			**Witness**	Charles Allen		
Photo #	1	**of**	1	**Date**	09/03/26	**Time**	0921
Description	The landfill east slope was observed.						

