

## NON-COMPLIANCE REPORT

Arkansas Department of Environmental Quality  
NPDES Enforcement Section  
5301 Northshore Drive  
North Little Rock, AR 72118

RE: NPDES Permit No: AR0021487 Discharge Number: 001

Facility: Van Buren Southplant

Address: 2806 Bryan Road

City: Van Buren State: AR Zip: 72957

Contact: Steve Dufresne, Director of Utilities Phone: 479-474-5067

| Date of Non-Compliance | Parameter Exceeded | Quantity or Loading | Quality or Concentration | Permit Limits  |
|------------------------|--------------------|---------------------|--------------------------|----------------|
| 5/1-3/2023             | Ammonia Nitrogen   |                     | 8mg/l (7 Day)            | 5 mg/l (7 Day) |
|                        |                    |                     |                          |                |
|                        |                    |                     |                          |                |
|                        |                    |                     |                          |                |

**We feel this problem was due to:**

Maintenance being done on blower #1

**We plan on correcting the problem in this manner:**

Replaced bearings and check valve on blower #1

**Time estimated that it will take to correct problem:**

The problem was corrected after repairs were done. The plant was in compliance the following week.

Sincerely,

  
Authorized Signature

6-14-2023  
Date