



CITY OF HOT SPRINGS

Utilities Department

780 Adams Street

Hot Springs, Arkansas 71901

June 12, 2026

Sent via email

Leslie Allen-Daniel
Enforcement Analyst – Water Division
Arkansas Energy & Environment – Environmental Quality
5301 Northshore Drive
North Little Rock, AR 72118-5317

RE: City of Hot Springs Utilities
Permit No. AR0033880 / AFIN 26-00145
Progress Report – Hot Springs Creek Pump Station

Dear Ms. Allen-Daniel,

Hot Springs Creek Pump Station, Manhole 1866

Max Foote Construction of Louisiana

Max Foote Construction has completed the installation of new pumps. The backup wet weather flow pump remains out of service while awaiting delivery of a new control panel from the vendor.

We continue to closely monitor the performance of the rehabilitated station and will promptly address any issues that arise.

System Performance

Hot Springs Utilities reported one brief SSO event at Manhole 1866 in May caused by an electrical problem. This issue was repaired.

Should you need further information, please contact Bobby Harris at (501)651-7734 or by email at BHarris@hotspringsar.gov.

Sincerely,

Bill Burrough

Bill Burrough
City Manager

Attachment: SSO Lab Results, Public Notification & Environmental Cleanup Documentation.

cc: **City of Hot Springs** - Denny McPhate, Deputy City Manager; Harold Mauldin, Wastewater Facilities Operations Manager; Joseph Statler, Assistant Utilities Project Manager; **Consultants** - Craig Johnson, Crist Engineers

MAY 2026 SSO REPORT – HS Creek & Manhole 1866

Manhole 1866 – 362 Fontana Road

Overflow Date: 5/6/2026
End Date: 5/6/2026
Cause: Rain and Equipment Failure
Discharge: Approximately 9,000 gallons discharged to Hot Springs Creek
Actions Taken: Environmental Cleanup, Hydro-cleanded, Disinfected, Deodorized, Raked/picked up and Spread Lime
CodeRed Issued: 5/6/2026
CodeRed Cancelled: 5/15/2026

Lab Results

Sample Date:	5/6/2026
Site No.	<i>E. coli</i> (cfu)
1	>2419.6

Sample Date:	5/8/2026
Site No.	<i>E. coli</i> (cfu)
2	56.1
3	21.1
4	50.4

Sample Date:	5/11/2026
Site No.	<i>E. coli</i> (cfu)
2	410.6
3	9.8
4	50.4

Sample Date:	5/13/2026
Site No.	<i>E. coli</i> (cfu)
2	3.0
3	1.0
4	15.6

CodeRed Notification Signage



620 Grand Point



After Removal



240 Matthews Drive



After Removal

ENVIRONMENTAL CLEANUP

HS Creek Pump Station & Manhole 1866 – 5/7/2026



Before



During



During



After